



(GA1) REPORT OF THOROUGH EXAMINATION OF LIFTING EQUIPMENT



This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 (LOLER) & Safety, Health and Welfare at Work (General Application) Regulations 2007 - SI. No. 299/2007 and The Work at Height Regulations 2005 when safety equipment is being inspected.

Date of Thorough Examination: 15/01/2020	Report #: 56277	Colour Code: Yellow	Job No: R14830
--	-----------------	---------------------	----------------

Name and Address of employer for whom the thorough examination was made: J COFFEY CONSTRUCTION LTD, 93-95 GREENFORD ROAD, HARROW, MIDDLESEX, LONDON ENGLAND, HA1 3QF	Address of premises at which the examination was made: FACEBOOK, CLONEE , CO MEATH
---	---

Description and identification of the equipment: MERLO P38-13 TELESCOPIC HANDLER - ZF1P33TC9C7001998 REG L019 FCC	Date of manufacture if known: 2018
---	---------------------------------------

Safe Working Load(s) (Kgs(Unless Otherwise Stated)) @2 MTS 3800 KG	Test Load Applied Kgs(Unless Otherwise Stated) N/A
---	---

Is this the first examination after installation or assembly at a new site or location?	Yes	No	Was the examination carried out: PERIODIC EXAMINATION Within an interval of 6 months? Within an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	Yes	No
		✓			✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect (If none state NONE): NONE
--

Is the above a defect which is of immediate danger to persons?	YES		NO	✓
--	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons (if YES state the date by when)	N/A
---	-----

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE
--

Identification of any parts not accessible for examination: NONE

Particulars of any tests carried out as part of the examination: (If none state NONE): VISUAL INSPECTION

Part Used

IS THIS EQUIPMENT SAFE TO OPERATE?	YES	✓	NO	
---	-----	---	----	--

Name / Signature of person making and authenticating this report with occupation: Tony Lally Competent, certified inspector. All certificates available on request.	Latest date by which next thorough examination must be carried out: 15/01/2021
---	---

Tony Lally